Sibelmed®

WEATHER STATION USB SIBELMED



34 x 70 x 12,5 mm.

KG 100 g.

Temperature

Pressure

Humidity

USB

www.sibelmed.com

USB SIBELMED · weather station

Description

The USB Sibelmed weather station measures the meteorological data of temperature, pressure amd humnidity with high accuracy.


	Range	Accuracy (%)
Temperature (ºC)	5 - 40	+/- 0.2
Pressure (mmHg)	250 - 1060	+/- 1,5
Humidity (%HR)	10 - 90	+/- 2

The weather station it is connected to the PC USB port and sends continuously the meteorological data.

It is compatible with the W20s software and therefore with all the Sibelmed spirometers.
The software collects the data form the station automatically each time a spirometry test or a callibration is done.

Plug & Play technology.

The station connects to the computer by USB cable, and the software automatically detects it. It does not require any installation or configuration.



Portable

Light and small accessory, that has a magnet to put it in the surface of the PC.

It measures the pressure, temperature and humidity

Automatic correction of the BTPS at the beginning of each test/calibration.

Blue LED

Indicates that the weather station is working.

No need of batteries

Powered by USB.

Compatible

With all Sibelmed spirometers and W20s versions 2.09 and later.

Valid for the Windows operating system

VISTA, 7, 8.1 y 10.

SIBEL S.A.U., Rosellón 500 bajos, 08026 BARCELONA (Spain)
National Sales: Tel. +34 93 436 00 08 e-mail: comercial@sibelmed.com
International Sales: Tel.+34 93 436 00 07 e-mail: export@sibelmed.com
Technical support: +34 93 433 54 50 e-mail: sat@sibelmed.com Fax: +34 93 436 16 11
www.sibelmed.com

CE EN 61010-1:2010 EN ISO 9001:2015

SIBEL S.A.U. reserves the right to modify the technical specifications without prior notice

FG-SIB-2008_EN - Estación Meteorológica - V1.0 - 01/2021